

Jack up Rig (Steel Work Repair)



Project: Cracks Repair, Gusset Plate Replacement, Brace Removal at Leg, Leg Well Bulkhead Renewal

Location: Johor Port Wharf 10, Johor

Date: September – December 2016